TRANBERG® WARNING LABEL

Type 5029 Caution- and End Seal Label

Heat Trace Accessories



Caution labels are intended for direct exposure to industrial environments.
Electrically heated pipelines and vessels should be clearly indentified at frequent intervals along the pipeline or vessel.

Apply caution label to insulation weather barrier at ca. 3 meter intervals

Heat trace end seal label should be placed directly above the end seal.

TRANBERG STAHL

THE STRONGEST LINK.

R. STAHL TRANBERG AS
Main office | Strandsvingen 6 | N-4032 Stavanger, Norway | **T** +47 51 57 89 00 | **E** info.no-st@r-stahl.com | stahl-tranberg.com
Oslo office | Luhrtoppen 2 | N-1470 Lørenskog, Norway | **T** +47 24 08 44 10 | **E** info.no-os@r-stahl.com | stahl-tranberg.com

TPS1021 REV. C 25.03.2022

Subject to change without prior notice

TRANBERG® WARNING LABEL

Type 5029 Caution- and End Seal Label

Heat Trace Accessories

Description	Weight	Part No.
End seal label	0,005 kg.	5029 1266
Caution label, Electric heat trace	0,005 kg.	5029 1265
Caution label, Electrical heat tracing splice kit	0,005 kg.	5029 1267

STAHL TRANBERG

R. STAHL TRANBERG AS

Main office | Strandsvingen 6 | N-4032 Stavanger, Norway | **T** +47 51 57 89 00 | **E** info.no-st@r-stahl.com | stahl-tranberg.com

Oslo office | Luhrtoppen 2 | N-1470 Lørenskog, Norway | **T** +47 24 08 44 10 | **E** info.no-os@r-stahl.com | stahl-tranberg.com