

TRANBERG® TAPE

Glass Tape

Heat Trace Accessories



Glass cloth tape for carbon steel pipes and stainless steel pipes.

Application

- Glass tape for attaching heating cable to pipe.

Advice

- If you must apply the tape during cold weather conditions, be sure to warm the tape first. You should also make sure that the surface is moisture free.



Description	Part No.
Recommended for stainless steel pipes:	
Fixing tape GS-54, Temp: below 5°C/ Max. 260°, length 16 meters	7000022
Recommended for other pipes:	2580542
Fixing tape GT-66, Temp: Min. 5°C / Max. 130°C, length 20 meters	7000021



R. STAHL TRANBERG AS

Main office | Strandsvingen 6 | N-4032 Stavanger, Norway | T +47 51 57 89 00 | E info.no-st@r-stahl.com | stahl-tranberg.com
Oslo office | Lohrtoppen 2 | N-1470 Lørenskog, Norway | T +47 24 08 44 10 | E info.no-os@r-stahl.com | stahl-tranberg.com